Boeing Commercial Airplane Group P.O. Box 3707 Seattle, WA 98124-2207 **RECEIVED**

AUG 2 3 1993

KING COUNTY
INTERNATIONAL AIRPORT

August 18, 1993 R-1150-93-SAC-703

Michael Gallagher Washington State Department of Ecology 3190 160th Avenue SE Bellevue, WA 98008-5452

BOEING

Dear Mr. Gallagher:

Subject: Independent Remedial Action - North Boeing Field Fire Training Facility

Enclosed is a copy of the Landau Associates Independent Remedial Action Report, North Boeing Field Fire Training Center, King County Washington. This report is submitted, as required, to update the Department of Ecology (Ecology) as to the status of this independent remedial action.

As indicated, the remedial activity at this site included excavation of petroleum impacted soil for offsite disposal at an approved facility and backfilling with clean material.

Analytical results from confirmation sampling indicate all petroleum impacted soils above MTCA Method A cleanup levels were removed as a result of this activity.

Visual observations indicated there may have been some impacted ground water in one portion of the excavation. However, we believe this impact was probably mitigated by the excavation of nearby soils. Further investigation of this localized area is being conducted to confirm these observations. Ecology will be notified as to the results of this action.

If you have any questions concerning this matter or need additional information please contact me or Brain Anderson at 477-2184.

Original signed by

L. M. Babich III Manager, Environmental Affairs Renton Division 234-1766, MS 63-41

Enclosure cc: Don Smith, King County Airport Manager

